


Choosing the Right Conductivity Sensor



Constant	Range
0.01	0 - 10 μS
0.1	0 - 500 μS/cm
0.5	0 - 2000 μS/cm
1	0 - 5000 μS/cm
10	0 - 50 mS/cm
50	0 - 200 mS/cm